Aviation Risk Solutions Inc.Birchwood BCV AirportInspection Report

Inspection date 6/9/2014



Aviation Risk Solutions Inc. provided this inspection service under contract to the State of Alaska Department of Transportation & Public Facilities Statewide Aviation Division. This report documents the findings of an onsite inspection using WAAS GPS receivers, digital photography and electronic laser distance and azimuth measuring equipment.

GPS coordinates on photos of Navaids, Facilities and Obstructions etc. indicate the actual coordinates of the subject. GPS coordinates on photos labeled as "View" indicate the actual coordinates of the perspective or location where the photo was taken. All indicated headings are Magnetic.

Runway dimensions and condition;

02L/20R 4010' x 100 asphalt in Fair condition due to faded markings and cracks in the surface. 02R/20L 2200' x 50 asphalt and gravel in fair condition due to faded markings, cracks in the surface and loose gravel.

Approach slope;

02L-21:176' trees 1647' from threshold, on both sides of centerline.

20R-20:1 55' trees 1112' from threshold, 120' left and right of centerline.

02R-21:1 77' trees 1622' from threshold, 180' right of centerline.

20L-32:1 65' trees 2088' from threshold, on both sides of centerline.


Navaids and lighting; two wind socks, one segmented circle, PAPIs on runways 02L/20R full runway and taxiway lighting.

Vegetation; brush and trees up to 80' high surrounding the airport.

Wildlife; moose, bears and migratory waterfowl in the vicinity.

Safety Issues; airport is not secure, vehicle and ATV traffic on runways and taxiways, pilots should exercise caution when operating at this airport.

Overview Map



Aerial viewView to the north west







Aerial ViewView to the west



















Facilities, AWOSLocated on west ramp












































































































































Navaid, windsock midfield, east side of runways













Road access to norh east ramp

View from road







Road access to west ramp







Road access, west ramp













Runway 02L controlling obstruction

76' trees, 1647' from runway end, on both sides of centerline. Approach slope 20:1































Runway 02R controlling obstruction.

77" trees, 1622' from runway end, 180' right. Approach slope 21:1



















Runway 02R midfield

Asphalt and gravel meet at this point

























View from taxiway

























Runway 20L/02R midfield

asphalt and gravel meet at this point.







Runway 20R at midfield taxiway













Runway 20R controlling obstruction

55' tree, 1112' from runway end, 120' right, approach slope 20:1







Runway 20R controlling obstruction

55' trees, 1112' from runway end, 120' left. Approach slope 20:1





































Signage, Approach end 20L, 20R, view from north east ramp







Signage, located on south east ramp

























TaxiwayView from west ramp







TaxiwayView from west ramp







TaxiwayView from 02L of west ramp




















Taxiway EView from 02L













Taxiway to 20RView from north east ramp









































